

FIG. 1B





FIG. 2




FIG. 3B





FIG. 3C

FIG. 4A





FIG. 4B



3/1

FIG. 5A





FIG. 5B



4/11

FIG. 7A




FIG. 7B





FIG. 6



U.S. Pat. No. 3,930,740 - Filed Dec. 18, 1973

FIG. 8




FIG. 9A





FIG. 9B






Fig. 10A




Fig. 10B




Fig. 10C

9 11
120 127 128
115C 115B 117
113 113A 114
112 116 110

FIG. 11




FIG. 12A





FIG. 12B






Fig. 13




Fig. 14

1111